

WAGNER[®] Brake Fax #2

WAGNER[®]
Brake Products

SERVICE TIPS FOR THE PROFESSIONAL TECHNICIAN

The #1 Choice

1984 Oldsmobile Cutlass Ciera Low Vacuum Condition

Some 4.3 L V-6 Federal Version 1984 Oldsmobile Cutlass Ciera models may experience a low vacuum condition causing the brake warning light to come on, particularly at idle. These vehicles are equipped with a low vacuum sensor at the vacuum booster and a belt driven vacuum pump. The low vacuum condition and subsequent brake warning light illumination may be caused by abrasion wear of the vacuum hose between the vacuum regulator and "tee" fitting.

If this condition exists, replace this portion of the hose with a 13-1/2" length of 7/32 vacuum hose after rotating the "tee" fitting to aim at the left front headlamp. The vacuum hose should then be routed in front of the EGR valve as illustrated below (dotted line).

